

Index: R-7 Corner: 1/4 LAND CORNER RECORD

State of Indiana
Hoosier National ForestTwnshp: 7N Range: 1E Section: 20/29 2nd P.M. County Monroe

EXISTING SURVEYS

Original Government Survey

Year Surveyed:	1814	By:	Arthur Henrie
Original Monument:	Wood Post		
Species	Diameter	Bearing	Distance
Ironwood	4"	N 15° E	7 links
Dogwood	4"	S 18° W	16 links

Original Survey Evidence Found

Date of Search:		By:	
Monument Found:			
Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Where Filed or Recorded:	Monroe County Surveyor's Office		
Book: 1	Page: 278	Date: 11/28/1854	
Monument Set:	Previous set post		
Species	Diameter	Bearing	Distance
None Stated			


Evidence of Subsequent Corner Restoration Found

Year Searched:	12/03/2013	By:	R. Siddens D. Norrington
Monument Found	3" Diam. Steel Pipe with 3" Diam. Brass Cap, 6" above ground, stamped as shown		
Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The monument is located approximately in the center of a southwest to northeast ridgetop. It is approximately 475 feet northeast of the Holland Pond and 43 feet north of a metal T-post with meandering east-west barbwire 4-strand fence (poor condition). The boundary line running east and west from this monument was originally blazed in 1978/79. On this date in 2013 we painted the three bearing trees, installed bearing tree signs, and installed carsonite line posts and painted tree blazes up to 500 feet west (to drainage) and 350 feet east (to ravine) of the monument. A carsonite survey marker post was set 2.0 feet south of the monument. The old wood 4"x4" sign post was found on the ground next to the monument. The coordinates shown at the bottom were collected using a resource grade Trimble GEO XT unit. The horizontal precision was 0.7 feet. (Photos below are (L) southeast view and (R) northwest view)	

PERPETUATION RECORD

Photographs of vicinity.	
	
Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.
	2003 Bearing Trees found and maintained:
	Poplar W. Oak B. Oak
	21" Diam. 19" Diam. 20" Diam.
	S 43° E S 00° W S 69° W
	33.1 Feet 39.1 Feet 15.0 Feet
	(Painted & Tagged) (Painted & Tagged) (Painted & Tagged)
	Corner Recordation: Certificate Prepared:
	Filed and Recorded in Date:
	County records:
	Book: Page:
Section: 29	IN State Plane Coordinates: N. 1374374.409 E. 3137418.915
	Edited By: Darren Norrington Date Created: 12/19/2013

Referenced on BRG survey recorded as InstNo.2005011737.

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 20

Township: 7 North


Range: 1 East

Corner ID: Polk G-17

Monument Description & Remarks: 3" Brass Disk 6" above ground. Survey Sign 5.5ft above ground at pt. B

References On File: Matthew Cooper survey, Boundary Survey for U.S. Department of Agriculture (2004), on file in Recorder Office cabinet S, envelope 285

RECOVERY TIE DRAWING
Field Book 39 Page No. 18




A - 3" Brass Disk
B - N 72° W 11.96' to Survey Sign on 7" Bifurcated Hickory
C - S 69° E 21.70' to MAG nail in 13" Red Oak
D - S 02° E 38.36' to MAG nail in 17" White Oak

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 2-11 of the Indiana Code; and the above data is given under my hand and seal this 2nd day of April, 2007.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board




Date: 4-17-2007

Index:	R-7	Corner:	S ¼	LAND CORNER RECORD				State of Indiana Hoosier National Forest	
Twnshp:	7N	Range:	1E	Section:	20/29	2 nd P.M.	County	Monroe	
EXISTING SURVEYS									
Original Government Survey					Original Survey Evidence Found				
Year Surveyed:	1814	By:	Arthur Henrie		Date of Search:		By:		
Original Monument:	Wood Post				Monument Found:				
Species	Diameter	Bearing	Distance		Species	Diameter	Bearing	Distance	
Ironwood	4"	N 15°E	7 links						
Dogwood	4"	S 18°W	16 links						
Subsequent Corner Restoration					Evidence of Subsequent Corner Restoration Found				
Where Filed or Recorded:	Monroe County Surveyors Office				Year Searched:	11/3/03	By:	B. Stone	
Book: 1	Page: 278	Date:	11/28/1854		Monument Found	3" Diameter FS monument steel pipe standing 6" above ground with a 3" diameter brass cap stamped as shown			
Monument Set:	previous set post								
Species	Diameter	Bearing	Distance		Species	Diameter	Bearing	Distance	
none	stated								

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc. The monument is located approximately in the center of a southwest to northeast ridgetop. It is approximately 390 feet northeast of Holland Pond and 43 feet north of a metal "T" fence post with meandering east –west barbwire 4 strand fence. The boundary line running east and west from the monument was blazed in 1978/79. Blazes are healed over. I repainted blazes up to 80 feet west of the monument.	Sketch of Monument 
---	--

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position. I tied up pink flagging and repainted red , the monument and small geode rock cairn.					
					
Corner Diagram		Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.			
		T. Poplar 19" S 43°E 33.1 Ft.			
		W. Oak (with 4 strands 19" barbwire) S 0°W 39.1 Ft.			
		B. Oak (with old healed 18" over blazes) S 69°W 15.0 Ft.			
		Corner Recordation:		Certificate Prepared:	
		Filed and Recorded in County records:		Date:	
Book:		Page:			
Section: 20		Geodetic Coordinates:		Lat./N.	39°01'11.470
		Edited By: Robert J. Stone		Long./E.	86°26'00.089
		Date Created:		11/06/2003	

Index No. R-7
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E Mer. N.F. Hoosier County Monroe State Ind
Corner common to sections 20, 29, and

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1874</u>		Year of search _____	By _____
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species <u>Ironwood</u> <u>Boxwood</u>		Species _____	
Diameter <u>4"</u> <u>2 1/2"</u>		Diameter _____	
Bearing <u>N 13 E</u> <u>S 18 W</u>		Bearing _____	
Distance <u>2 1/2</u> <u>16 1/2</u>		Distance _____	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed _____	By _____	Year of search _____	By _____
Where filed or recorded _____			
Monument _____ (Original, concrete post, iron rod, etc.)			
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species _____			
Diameter _____			
Bearing _____			
Distance _____			



Sketch

○ Corner ☒ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area.
Found fence running E-W Found tree line from S.

At time of search:

1. Did you have the record description?
Yes ☒ No _____

2. How was search area located?
Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 2 hrs.

4. Do you think additional search might recover evidence? Yes _____ No ☒

5. Signature J. Deaton

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

